BOILER & PROCESS HEATER TUNE-UP REPORT

Location: Ignacio Regen Heater	Tune-up Date: 1-25-18
Equipment Description (Make/Model): CE Natco	Operating Permit Unit ID: V-SUIT-0027-2017.00
Heat Input Capacity (MMBtu/hr): 18.5	
Tune-Up Tasks	Record measurements below
Measure the concentrations in the effluent stream of CO in parts per million (ppm) and oxygen in volume percent using a portable electrochemical cell emissions analyzer, before and after any adjustments are made, as required by tasks below. NOx measurement is not required but if measured should be recorded. If no adjustment required, post adjustment measurement can be the same as pre adjustment (as found) measurement.	Pre Adjustment Measurement Oxygen % 2.2 CO (ppm) 1539 NOx (ppm) 12 Post Adjustment Measurement Oxygen % 2.2 CO (ppm) 1539 NOx (ppm) 12 Measurement Legation (Port or stack exit)
Conduct the following <u>during</u> unit operation. If inspection indicates components require cleaning or replacement, work should be conducted prior to the next required tune-up. Inspect the burner(s) for signs of heat stress, corrosion or other signs of wear which may indicate burner malfunctioning.	Port Record the following in tuning notes section below.
Inspect the flame pattern during operation via viewing window/porthole.	Burner and oxygen trim system inspection results. As found flame pattern, color, length, impingement.
 Adjust the burner as necessary to optimize the flame pattern. If flame isn't viewable, rely on emission measurements as performance indicator. 	If adjustments were made, note conditions of the following as left: Flame pattern, color, length, impingement;
 Inspect the system controlling the air to fuel ratio (oxygen trim system). If air to fuel ratio is controlled manually, no inspection is necessary. Ensure that the system is correctly calibrated and functioning properly 	Damper or louver position, oxygen trim system settings, fuel pressure If maintenance issues or deficiencies arise during inspection, make note of work order request for further inspection/repair below.
Tuning Notes: Work Performed By: David Shupe & Steve Richa	

File report with air quality compliance records for facility